

SITUACIÓN DEFICIENCIAS DETERMINADAS PREVIO ☒ DURANTE ☐ POSTERIOR ☐

DEPARTAMENTO:	PETÉN	MUNICIPIO:	SAN ANDRÉS
NOMBRE DEL ESTABLECIMIENTO:	INEB DE TELESECUNDARIA	DIRECCIÓN DEL ESTABLECIMIENTO:	CASERÍO CRUCE PERDIDO
CÓDIGO DEL ESTABLECIMIENTO:	17-04-2725-45	FECHA:	10/9/2025



Foto 1: Mantenimiento a estructura (lijado, cambio de tubo, cepillado, sujeciones, aplicación de pintura)



Foto 2: Fabricación e instalación de marcos de aluminio mil finish



Foto 3: Mantenimiento a balcones de metal



Foto 4: Instalación de piso cerámico



Foto 5: Pintura en muros exteriores e interiores



Foto 6: Reparación de muro perimetral de block

Observación: Si es necesario se pueden agregar hojas adicionales y actualizar el número de hojas.

SANTIA ROSALES

Firma y sello del Presidente de la OPR



[Firma]

Firma y Sello Director Centro Educativo Público





 A black and white photograph of a large, multi-story building with a prominent central tower and arched windows, possibly a university hall.	 A black and white photograph of a building with a gabled roof and a chimney, surrounded by trees.
 A black and white photograph of a large, open field or park with trees in the background.	 A black and white photograph of a building with a prominent chimney and a gabled roof, similar to the one in the top right.
 A black and white photograph of a small, single-story building with a chimney.	 A black and white photograph of a long, low building with a series of windows, possibly a classroom or lecture hall.
 A black and white photograph of a building with a gabled roof and a chimney, similar to the one in the top right.	 A black and white photograph of a building with a gabled roof and a chimney, similar to the one in the top right.

SITUACIÓN DEFICIENCIAS DETERMINADAS

PREVIO ☒

DURANTE ☐

POSTERIOR ☐

DEPARTAMENTO:	PETÉN	MUNICIPIO:	SAN ANDRÉS
NOMBRE DEL ESTABLECIMIENTO:	INEB DE TELESECUNDARIA	DIRECCIÓN DEL ESTABLECIMIENTO:	CASERÍO CRUCE PERDIDO
CÓDIGO DEL ESTABLECIMIENTO:	17-04-2725-45	FECHA:	10/9/2025



Foto 7: Sustrución de ducto elétrico + accesorios



Foto 8: Sustrución de tomacorrientes Dobles




Foto 9:




Foto 10:





Foto 5:



Foto

Observación: Si es necesario se pueden agregar hojas adicionales y actualizar el número de hojas.

<i>SantiaGo Rojas</i> Firma y sello del Presidente de la OPF	<i>[Firma]</i> Firma y Sello Director Centro Educativo Público
--	--

